



## Building X

September 2012





## CONTENTS

	<b>Page</b>	<b>Doc Ref</b>
Site Inspection Report (Including photographs)	3-17	n/a
Survey Plan	18	1.1
Pricing Schedule	19	1.2

This report has been prepared for XXX Builders and and is not for third party use.

# **MAINTENANCE OF EXTERIOR JOINERY**

## **A SITE INSPECTION REPORT**

### **Building X, Reading**

**Site Address:** Building X

**Reference:** 1

**Inspection Date:** 2012

**Conducted By:** Repair Care International Ltd

**At the expense of:** Repair Care International Ltd

**Inspection requested by:**

XXX Builders

## **INTRODUCTION**

The purpose of this Site Inspection report is to provide an outline of the recommendations by Repair Care International for the pre-paint repairs.

A photographic section illustrates many of the problems with existing joinery.

## **INSPECTION DETAILS**

Inspection was undertaken on all joinery except where access was not possible. It is limited to repairs that can be undertaken using the Repair Care System although some references are made to other items of window joinery.

## **DECORATIVE FINISH**

The decorative coating appears to be of a traditional oil based gloss system that has in places deteriorated, embrittled, lost adhesion, cracked or peeled. This is especially noticeable on lower horizontal components, e.g. cills

There are many open joints where the paint system has cracked, allowed moisture ingress causing wood decay and often subsequent premature paint failure.

Remaining intact paint coatings may be trapping moisture and camouflaging insitu decay.

Bare areas have become grey and denatured.

## **GLAZING**

The joinery inspected featured linseed oil putty in a face glazing situation.

The putty has become hard and embrittled with many cracks at 90° across the putty fillet. In some areas the putty is loose and trapping moisture.

The putty fillet has, in places, especially lower horizontal glazing lines, lost adhesion and fallen out.

Paint adhesion to putty is reduced and bare areas have allowed the denaturing of bare wood.

Internal glazing lines may allow moisture ingress.

## **OPEN JOINTS**

Open joints are apparent especially on lower sections of timber joinery, e.g. sash joints, mullion/cill intersections, style/rail joints, and around previous splice repairs.

Effective sealing will reduce the incidence of future insitu decay and assist the durability of the paint system.

## **AREAS SHOWING WOOD DECAY**

These areas include: -

- Previous Splice Repairs
- Cill Sections
- Bottom of Frames
- At Open Joints
- Jamb/Cill Joints
- Previous Repairs Using Filler
- Exterior frame linings

## **ADDITIONAL OBSERVATIONS**

Various properties are fitted with draught proofing of differing types, probably fitted by individual property owners.

We would recommend thorough mechanical sanding of the failed paint system to remove all grey degraded wood.

Our recommendations are designed to make good existing faults in the windows and to improve their durability and that of the paint system and so reduce future maintenance costs. E.g. where bottom rails have dropped but are still functioning we are looking to stabilise the situation rather than remove and replace.

Hardwood and softwood cills are fitted.

Some parting beads will require replacement.

## **CONCLUSION**

Effective repairs and preventative maintenance measures can be achieved without major disruption by using methods and tools available through Repair Care International.

## **RECOMMENDATIONS**

### **(a) DECORATIVE FINISH**

In view of the overall condition of existing paintwork, we suggest removal of paint from the bottom third of the window or back to the joint of each timber member; this will have the additional benefit of exposing hidden decay, enbrittled filler, etc. However account should also be taken of the paint manufacturers recommendations.

Minimum paint removal should be 10mm around the joinery section to be repaired. Loose paint and grey denatured wood must be sanded back to bright wood: - Consider using the Repair Care Sander

### **(b) GLAZING**

Internal glazing lines should be inspected for decay and mastic failure and sealed and repaired as appropriate.

Renew existing failed putty/mastic using Repair Care Dry Seal in full accordance with the appropriate section of Working Method PG2.

**NB.** The glazing rebate must be primed and allowed to dry before application of Dry Seal.

The glass under the previous putty must be clean and dry.

### **(c) OPEN JOINTS**

Seal any fascia board, butt joints and mitre joints in full accordance with Working Method P2.

Effectively seal all open lower construction joints in full accordance with Working Method P2 using the Repair Care Round Cutter to a depth of 10mm.

If any areas exhibit signs of insitu decay they must be restored in full accordance with Working Method C1/C3.

(d) **WOOD DECAY**

Areas of wood decay up to 400cm<sup>3</sup> should be repaired in full accordance with Working Method C1/C3 (Resin Repair) or Working Method C4 if appropriate.

Areas of wood decay over 400cm<sup>3</sup> should be repaired in full accordance with Working Method C4 (Resin and Timber Repair) or C2 as appropriate.

Previous splice repairs should be checked, if sound seal all around in accordance with Working Method P2. If subject to further decay or loose, remove and replace in accordance with Working Method P2 or C4.

Any previous repairs undertaken using traditional filler should be inspected and repaired in accordance with a suitable Working Method.

- (e) **NB.** Repairs must be left in a condition suitable for redecoration, preferably primed.
- (f) All contractors who are expected to carry out the work should be familiar with the System prior to tendering and be fully trained before commencing on site.
- (g) The Specifier could advise Repair Care International when the work is due to start so that on site quality control checks can be arranged.
- (h) The attached "Scope of Work" documents are offered for **guidance only**. They must not be taken as an indication of final quantities or sizes; however they may assist in obtaining contract prices or schedules of rates. The full extent of work will only become apparent when paint is removed and repair work is undertaken.
- (i) We recommend the use of the Dulux Weathershield Stain/Paint System.

Contact ICI direct or Repair Care to arrange for a Dulux Specification Account Manager to contact you with further information.

## **GUIDANCE NOTES FOR PRICING PURPOSES**

### **This contract anticipates:**

A full Repair Care System contract involving removal of paint from the lower 1/3 of windows and horizontals, the sealing of all construction joints in these areas and other vulnerable horizontal section joints. All failed glazing lines to be repaired using Dry Seal and wood decay repairs to be undertaken using Dry Flex resin or Dry Flex resin and timber as appropriate for best value.

A schedule of rates based on all types and sizes of Repair Care repairs is recommended.

Two 50cc resin (C1) repairs are included in the survey to cover any repairs camouflaged by the decorative coating.

Splices are sized to the nearest on the Survey sheet.

**All work to be undertaken in accordance with Repair Care Systems recommendations.**



# Photographic Section

Building X



Front Elevation – South facing



Typical window design



Typical window design



Arched window



Typical window design



Walkway extension to East elevation (No access)



Example of failed putty, open joints and deteriorating paint



Example of failed putty lines



Gap between glass and putty allowing moisture ingress



Decay to glazing bar and failed putty



Decay to outer sash lining



Decay to the cill, failed paint and an open sash construction joint



Open construction joint and horizontal split to the timber



Extensive decay to East elevation covered walkway



Failed putty, paint and a bracket used to repair a failed joint





Splits in timber front doors



Infestation found on fascias North and West facing

## **SURVEY PLAN**

Please see attached Document Ref 1.1 – Survey Plan

## **PRICING SCHEDULE**

Please see attached Document Ref 1.2 – Price schedule worksheet